



School Radon Training & Support System 2025–26 School District Radon Testing Report

District: CAM CSD **Report Date:**

Address: 1000 Victory Park Road, Anita, IA, 50020 **Phone:** 7127467060

Superintendent: Pam Stangeland **Email:** pstangeland@cam.k12.ia.us

Congratulations on preventing lung cancer in your school district and meeting the requirements of the Gail Orcutt School Radon Safety Act (Iowa House File 2412) by testing for radon. You now have peace of mind that your students, staff and community are learning in spaces that test below the U.S. Environmental Protection Agency's radon action level of 4.0 pCi/L. Thank you!

This School District Radon Testing Report and attached Radon Testing Results Summary by Building(s) provide a nutshell of test results to share on your website. With this report, your 2025–26 radon testing is officially complete. However your school radon rep, Julie Weisshaar, will continue to be here for you throughout the year to answer any additional questions at juliew@energyais.org or (515) 635-3277.

1.	Does the public school district have a radon plan and schedule for short-term tests for radon gas to be performed at each attendance center under its control at least once by July 1, 2027, and at least once every five years thereafter?	Y
2.	Does the public school publish (radon) testing results on the district's internet site in a timely manner?	Y
3.	Have district employees who conducted testing completed a school radon testing training program approved by the department of education and the department of public health? Name of program: School Radon Training & Support System through Energy Association of Iowa Schools	Y
4.	Were second short-term tests for radon conducted in spaces with results at or above four picocuries per liter within sixty days of the first test?	Y
5.	Was a radon mitigation plan developed within two years of the first test if averaged results of first and second tests were at or above four picocuries per liter?	N
6.	Was the corrective measure(s) and/or active mitigation identified in the developed radon mitigation plan to bring results below 4pCi/l completed within two years.	N/A
7.	All new school construction in our public school district will incorporate radon resistant construction techniques.	Y

Thank you for participating in the 2025–26 School Radon Training & Support System. We hope we have earned the opportunity to work with you again in the future.

Name	Jr/Sr High	District	CAM CSD
Address	1000 Victory Park Road IA, Anita, 50020	Scope	☒ All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Travis Dorsey	Phone	5152381200
# Test Kits Used	44	Dates	01/26/2026 - 01/29/2026

Test Results

Test 1:	# Rooms Tested:	34	#Rooms 4.0 pCi/L or above:	0
---------	-----------------	----	----------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

No further testing is necessary for 5 years or per district's School Radon Plan Testing Rotation Calendar.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Name	North Elementary	District	CAM CSD
Address	709 McIntyre Dr IA, Anita, 50020	Scope	☒ All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Travis Dorsey	Phone	5152381200
# Test Kits Used	15	Dates	01/26/2026 - 01/29/2026

Test Results

Test 1:	# Rooms Tested:	12	#Rooms 4.0 pCi/L or above:	0
---------	-----------------	----	----------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

NOTE: The classroom section of this building attached to the gym was torn down, therefore this building will not be tested for radon in the future.

The connected building that was used as a gym is now used as a daycare and for wrestling practice. This separate building space has been mitigated for radon, and will continue to be tested every 2 years.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Name	Wood Shop (abandon?)	District	CAM CSD
Address	408 Walnut IA, Anita, 50020	Scope	☒ All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Travis Dorsey	Phone	5152381200
# Test Kits Used	9	Dates	01/26/2026 - 02/19/2026

Test Results

Test 1:	# Rooms Tested:	4	#Rooms 4.0 pCi/L or above:	4
Test 2:	# Rooms Tested:	4	#Rooms 4.0 pCi/L or above:	0

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

The average of two test result(s) was at or above 4 pCi/l, which necessitates actively mitigating this building for radon if it will remain occupied by students.

However it was noted that CAM CSD is considering no longer using this small building as a learning space for students. If this ends up being the case, mitigation would be unnecessary.

Iowa Code 280.32 says that radon elevations must be fixed within two years of the first radon test, unless the building will be abandoned within five years.

EAIS will check in with CAM CSD about the status of this situation in the fall of 2026.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Name	N Daycare/Wrestling (mit)	District	CAM CSD
Address	709 McIntyre Dr IA, Anita, 50020	Scope	☒ All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Travis Dorsey	Phone	5152381200
# Test Kits Used	5	Dates	01/26/2026 - 01/29/2026

Test Results

Test 1:	# Rooms Tested:	1	#Rooms 4.0 pCi/L or above:	0
---------	-----------------	---	----------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

Mitigated spaces must be tested at 2-year intervals for a period of 8 years to ensure continued effectiveness.

After 8 years, if the mitigation system has consistently demonstrated keeping radon levels below 4 pCi/l, protocol allows discontinuing the bi-annual testing as long as the mitigation system is:

- a. Inspected quarterly to verify fan operation,
- b. Inspected biennially for mechanical equipment performance and integrity, and
- c. Enrollment centers and mitigated areas are retested every 5 years.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!